




Passen = Schrauben.

Maßstab 1:1.




Form 93.

60/16.






Form 5.

90/20.






Form 112.

115/22.






Form 157.

90/22.






Form 6.

100/26.



Form 172.

105/22.



Einmessen

Mendt den 6/2 1928.
Kahn.

FR 12 FR 12