


Stütz 3,50

22+55

Stütz 106,46
S.D. 105,84




Stütz 0,30
Stütz 2,00

22+83,22

B.M.

Stütz 106,84
S.D. 106,40



23+10


Stütz 107,17
S.D. 106,78
+0,39



Stütz 0,20
Stütz 0,10

23+50

Stütz 107,67
S.D. 107,64
+0,03



Stütz 0,20
Stütz 0,10

24+0

Stütz 108,33
Stütz 108,30
-0,03

